
Extruder 0 Motor Thermistor 0 Y Stop Hot End Heater Z Stop X Stop **Print Fan** Incoming Power X Axis Z Axis Motor Motor Y Axis Motor

RAMPS 1.4 WIRING presented by IMADE3D.com



RAMPS 1.4 WIRING

presented by MADE3D.com